

P16N station #1 (V7) Figure 11

LADCP WARNINGS

increased error because of shear – inverse difference

LADCP processing warnings:

large up/down bias ($u=0.01\text{m/s}$; $v=0.02\text{m/s}$) ---- GPS problems?

Battery Voltage is 64.8 V