

**P06 station #200 (V2) Figure 11**

**LADCP WARNINGS**

**broken down looking beam 3**

**increased error because of shear - inverse difference**

**LADCP processing warnings:**

**first LADCP depth is -186**

**large up/down bias (u=0.00m/s; v=3.25m/s) --- GPS problems?**

**Battery Voltage is 46.2 V**