

rh11151 (LADCP #123; V5) Figure 11

LADCP WARNINGS

**** found 1051 (9.5% of total) velocity measurements > 2.5 m/s**

increased error because of shear – inverse difference

LADCP processing warnings:

Battery Voltage is 68.7 V