

rh11201 (LADCP #130; V5) Figure 11

LADCP WARNINGS

increased error because of shear – inverse difference

LADCP processing warnings:

Battery Voltage is 67.4 V