

rh11261 (LADCP #136; V5) Figure 11

LADCP WARNINGS

increased error because of shear – inverse difference

LADCP processing warnings:

Battery Voltage is 67.7 V