

rh11641 (LADCP #177; V5) Figure 11

LADCP WARNINGS

**** found 220 (2.6% of total) velocity measurements > 2.5 m/s**

increased error because of shear – inverse difference

LADCP processing warnings:

Battery Voltage is 66 V