

P06 station #114 (V2) Figure 11

LADCP WARNINGS

broken down looking beam 3

increased error because of shear - inverse difference

LADCP processing warnings:

large up/down bias (u=0.00m/s; v=1.84m/s) --- GPS problems?

Battery Voltage is 45.8 V