

P06 station #116 (V2) Figure 11

LADCP WARNINGS

broken down looking beam 3

increased error because of shear - inverse difference

LADCP processing warnings:

large up/down bias ($u=0.00\text{m/s}$; $v=-0.06\text{m/s}$) --- GPS problems?

Battery Voltage is 46 V