

**rh11181 (LADCP #128; V5) Figure 11**

**LADCP WARNINGS**

**increased error because of shear – inverse difference**

**LADCP processing warnings:**

**Battery Voltage is 67.8 V**