

**rh11211 (LADCP #131; V5) Figure 11**

**LADCP WARNINGS**

**increased error because of shear – inverse difference**

**LADCP processing warnings:**

**Battery Voltage is 67.4 V**