

I08S station #87 (V2) Figure 11

LADCP WARNINGS

shifted ADCP timeseries by 14 seconds

Large compass deviation: 50.7512

increased error because of shear – inverse difference

LADCP processing warnings:

Battery Voltage is 52.2 V