

I08S station #90 (V2) Figure 11

LADCP WARNINGS

Large compass deviation: 47.0643

increased error because of shear – inverse difference

LADCP processing warnings:

Battery Voltage is 52.3 V