

I08S station #104 (V2) Figure 11

LADCP WARNINGS

Large compass deviation: 32.5118

increased error because of shear – inverse difference

LADCP processing warnings:

Battery Voltage is 51.9 V