

P06 station #139 (V2) Figure 11

LADCP WARNINGS

**** found 108 (0.9% of total) velocity measurements > 2.5 m/s**

broken down looking beam 3

increased error because of shear - inverse difference

LADCP processing warnings:

large up/down bias (u=0.00m/s; v=0.03m/s) --- GPS problems?

Battery Voltage is 46.2 V