P06 station #157 (V2) Figure 11

LADCP WARNINGS

Warning: cast duration differs in downlooker/uplooker data broken down looking beam 3 increased error because of shear - inverse difference

LADCP processing warnings:

Battery Voltage is 46 V