

I6S station #33 (V5) Figure 11

LADCP WARNINGS

weak down looking beam 1

LADCP processing warnings:

first LADCP depth is -919

large up/down bias ($u=2.02\text{m/s}$; $v=-0.36\text{m/s}$) --- GPS problems?

> Increasing error estimate because of elevated shear - inverse difference

Battery Voltage is 49.7 V