

P06 station #248 (V2) Figure 11

LADCP WARNINGS

weak down looking beam 3

Large compass deviation: 41.1801

increased error because of shear - inverse difference

LADCP processing warnings:

Battery Voltage is 52.9 V