

P06 station #168 (V2) Figure 11

LADCP WARNINGS

Warning: cast duration differs in downlooker/uplooker data

**** found 108 (1.2% of total) velocity measurements > 2.5 m/s**

broken down looking beam 3

increased error because of shear - inverse difference

LADCP processing warnings:

large up/down bias (u=0.00m/s; v=-0.05m/s) --- GPS problems?

Battery Voltage is 46.1 V