

## **P06 station #145 (V2) Figure 11**

### **LADCP WARNINGS**

**\*\* found 270 (2.1% of total) velocity measurements > 2.5 m/s  
broken down looking beam 3  
increased error because of shear - inverse difference**

**LADCP processing warnings:**

**Battery Voltage is 45.7 V**