

P06 station #178 (V2) Figure 11

LADCP WARNINGS

**** found 122 (1.3% of total) velocity measurements > 2.5 m/s
broken down looking beam 3
increased error because of shear - inverse difference**

LADCP processing warnings:

Battery Voltage is 46.4 V