

I7N station #5 (V2) Figure 11

LADCP WARNINGS

broken down looking beam 1

increased error because of shear - inverse difference

LADCP processing warnings:

Battery Voltage is 41.8 V