

P06 station #158 (V2) Figure 11

LADCP WARNINGS

**Warning: cast duration differs in downlooker/uplooker data
broken down looking beam 3
increased error because of shear - inverse difference**

LADCP processing warnings:

Battery Voltage is 46.1 V