

P06 station #180 (V2) Figure 11

LADCP WARNINGS

**** found 127 (1.5% of total) velocity measurements > 2.5 m/s
broken down looking beam 3
increased error because of shear - inverse difference**

LADCP processing warnings:

large U bottom track bias -0.11528

Battery Voltage is 46.4 V