P16N station #25 (V7) Figure 11

LADCP WARNINGS

** found 302 (2.9% of total) velocity measurements > 2.5 m/s increased error because of shear – inverse difference

LADCP processing warnings:

Battery Voltage is 64.7 V