P16N station #167 (V7) Figure 11

LADCP WARNINGS

** found 155 (1.8% of total) velocity measurements > 2.5 m/s increased error because of shear – inverse difference

LADCP processing warnings:

Battery Voltage is 58.4 V