P06 station #129 (V2) Figure 11 LADCP WARNINGS

Warning: cast duration differs in downlooker/uplooker data ** found 122 (1.0% of total) velocity measurements > 2.5 m/s broken down looking beam 3 increased error because of shear - inverse difference

LADCP processing warnings:

Battery Voltage is 46.5 V