rh11801 (LADCP #193; V5) Figure 11

LADCP WARNINGS

** found 110 (1.3% of total) velocity measurements > 2.5 m/s

LADCP processing warnings:

Battery Voltage is 65.7 V