I7N station #37 (V2) Figure 11

LADCP WARNINGS

** found 102 (1.1% of total) velocity measurements > 2.5 m/s

weak down looking beam 1

broken up looking beam 3

increased error because of shear - inverse difference

LADCP processing warnings:

Battery Voltage is 54.7 V