

I6S station #1 (V5) Figure 11

LADCP WARNINGS

weak down looking beam 1

LADCP processing warnings:

large up/down bias ($u=-0.00\text{m/s}$; $v=-2.34\text{m/s}$) --- GPS problems?

Battery Voltage is 57.8 V