A20 station #54 (V7) Figure 11

LADCP WARNINGS

LADCP processing warnings:

> Increasing error estimate because of elevated shear - inverse difference

Battery Voltage is 45.2 V