P2E station #11701 (V7) Figure 11 LADCP WARNINGS

LADCP processing warnings:

> Increasing error estimate because of elevated shear - inverse difference

Battery Voltage is 39.4 V