

**P06 station #207 (V2) Figure 11**

**LADCP WARNINGS**

**Warning: cast duration differs in downlooker/uplooker data  
broken down looking beam 3  
increased error because of shear - inverse difference**

**LADCP processing warnings:**

**Battery Voltage is 46.3 V**