

I7N station #30 (V2) Figure 11

LADCP WARNINGS

weak down looking beam 1

broken up looking beam 3

increased error because of shear - inverse difference

LADCP processing warnings:

Battery Voltage is 53.2 V