S4P station #96 (V8) Figure 11

LADCP WARNINGS

** found 119 (1.0% of total) velocity measurements > 2.5 m/s increased error because of shear - inverse difference

LADCP processing warnings:

Battery Voltage is 61.8 V