

P06 station #205 (V2) Figure 11

LADCP WARNINGS

broken down looking beam 3

LADCP processing warnings:

large up/down bias (u=0.00m/s; v=-0.21m/s) --- GPS problems?

Battery Voltage is 46.3 V