

P06 station #155 (V2) Figure 11

LADCP WARNINGS

Warning: cast duration differs in downlooker/uplooker data

**** found 119 (1.0% of total) velocity measurements > 2.5 m/s**

broken down looking beam 3

increased error because of shear - inverse difference

LADCP processing warnings:

Battery Voltage is 46.1 V