## I7N station #41 (V2) Figure 11

- LADCP WARNINGS
  - weak down looking beam 1
  - broken up looking beam 3
- increased error because of shear inverse difference

LADCP processing warnings:

Battery Voltage is 54.5 V