

rh11861 (LADCP #199; V5) Figure 11

LADCP WARNINGS

**** found 180 (2.0% of total) velocity measurements > 2.5 m/s**

LADCP processing warnings:

Battery Voltage is 65.5 V