I7N station #13 (V2) Figure 11

- LADCP WARNINGS
 - broken down looking beam 1
 - broken up looking beam 3
- increased error because of shear inverse difference

LADCP processing warnings:

Battery Voltage is 45.4 V