

I7N station #23 (V2) Figure 11

LADCP WARNINGS

**** found 117 (1.3% of total) velocity measurements > 2.5 m/s**

broken down looking beam 1

broken up looking beam 3

LADCP processing warnings:

Battery Voltage is 46.4 V