

## **I7N station #19 (V2) Figure 11**

### **LADCP WARNINGS**

**\*\* found 142 (1.5% of total) velocity measurements > 2.5 m/s**

**broken down looking beam 1**

**broken up looking beam 3**

**LADCP processing warnings:**

**Battery Voltage is 46.1 V**