## I7N station #29 (V2) Figure 11

## **LADCP WARNINGS**

weak down looking beam 1

broken up looking beam 3

increased error because of shear - inverse difference

**LADCP** processing warnings:

**Battery Voltage is 52.6 V**